

**APPENDIX A: MATERIAL ASSESSMENT SHEETS**

<b>Site ID</b>	21051	<b>Floor</b>	GROUND
<b>Location ID</b>	1051/037	<b>Room / Area</b>	WORKSHOP PARTITION
<b>Building</b>	EAST WORKS	<b>Description</b>	BOARDING ABOVE WINDOWS



<b>Surveyed</b>	YES	<b>Source Of Information</b>	CLIENT
<b>Last Inspection Date</b>	06/May/2004	<b>Lab Reference</b>	32011/37
		<b>Sample Number</b>	1051/037

**Survey Type** TYPE 2 - SAMPLING

**MATERIAL ASSESSMENT = 7**

<b>Material</b>	INSULATION BOARD	<b>Surface Treatment</b>	UNSEALED AIB
-----------------	------------------	--------------------------	--------------

<b>Condition</b>	LOW DAMAGE	<b>Sample Result</b>	AMOSITE
------------------	------------	----------------------	---------

**Location** INTERNAL (OCCUPIED)

**Accessibility** LOW

**Amount** 8 linear / square metres

**MANAGEMENT SUMMARY**

<b>Action</b>	REPAIR / ENCAPSULATE	<b>Priority</b>	1	<b>Notifiable</b>	YES
<b>Comments:</b>	IN GENERAL GOOD CONDITION BUT WITH SMALL AREAS OF DAMAGE.				
<b>Recommendations:</b>	LICENSED CONTRACTOR TO PAINT WITH SEALANT PRIOR TO LABELLING.				