

**RISK ASSESSMENT SHEETS FOR SELECTED LOCATIONS**

<b>Site ID</b>	21051	<b>Floor</b>	GROUND
<b>Location ID</b>	1051/136	<b>Room / Area</b>	MACHINE SHOP
<b>Building</b>	R & D EAST WORKS	<b>Description</b>	CEILING BOARDS TO THE EDGE



<b>Surveyed</b>	YES	<b>Source Of Information</b>	CLIENT
<b>Last Inspection Date</b>	25/May/2004	<b>Lab Reference</b>	32377/31
		<b>Sample Number</b>	1051/136
<b>Survey Type</b>	TYPE 2 - SAMPLING		
<b><u>MATERIAL ASSESSMENT = 5</u></b>			
<b>Material</b>	INSULATION BOARD	<b>Surface Treatment</b>	ENCAPSULATED AIB
<b>Condition</b>	GOOD	<b>Sample Result</b>	AMOSITE CHRYSOTILE
<b><u>RISK ASSESSMENT = 10</u></b>			
<b>Main Activity</b>	RARE DISTURBANCE ACTIVITY	<b>Number of Occupants</b>	>10
<b>Secondary Activity</b>	RARE DISTURBANCE ACTIVITY	<b>Frequency of Use</b>	DAILY
<b>Location</b>	INTERNAL (OCCUPIED)	<b>Average Time in Use</b>	>=6 HOURS
<b>Accessibility</b>	LOW	<b>Maintenance Activity</b>	MINOR DISTURBANCE ACTIVITY
<b>Amount</b>	10 linear / square metres	<b>Maintenance Frequency</b>	UNLIKELY TO BE DISTURBED
<b><u>MANAGEMENT SUMMARY</u></b>			
<b>Action</b>	MANAGE / LABEL	<b>Priority</b>	3
<b>Comments:</b>	AT HIGH LEVEL ABOVE THE FIRE EXIT.		
<b>Recommendations:</b>	LABEL WITH APPROPRIATE ASBESTOS WARNING SIGNS.		